


Drawing by Glenn Bruner
 Drawing revised on 21 Oct 2000
 - fixed SRAM location ID's
 - added SRAM information
 Drawing revised on 19 Nov 2000
 - updated SRAM information
 - fixed error on /CE signal destination

Jumpers are set for 2MB version
 Move JP6, JP7, and JP8 for 4MB version
 when using TC554001, HM628512, or KM684000 SRAM
 Hitachi HM628512ALFPI-7, -8
 Hyundai HY628400ALG-7, -8
 Samsung K6T4008C1B-GL70
 Toshiba TC554001FL-70V, -85V, -10V
 SRAM Package Type: SOP 32-pin, 525-mil



B1 - B5 are part of STOP CABLE